


# REPAIR YOUR PIPES FROM THE INSIDE WITH NUFLOW.

NuFlow is a proven pipe lining technology that restores and renews old, broken or corroded pipes to a "like new" condition without the need to remove or replace them. Our NuDrain cured-in-place pipe lining process does not require any digging or destruction to your property and therefore translates to less mess, less cost, and minimal disruption to your daily lifestyle.




## STEP 1: INSPECTION

Inspect the existing pipes for any corrosion, roots, or cracks using a drain camera.



## STEP 2: CLEANING

Debris, roots and corrosion are removed from the pipes using NuFlow's proprietary tools.



## STEP 3: LINING

NuFlow liner is pulled into the pipe and cures in place, creating a clean, strong "pipe within a pipe". A final inspection is performed for quality assurance.

**nuflow**  
WE FIX PIPES

[www.nuflowtech.com](http://www.nuflowtech.com) | 800.834.9597



### Hidden Valley Home: Underground Drain Line Rehabilitation

**LOCATION:** La Jolla, California

**SITUATION:** The customer's sanitary system experienced chronic backups due to heavy root intrusion in the pipeline. This 4" clay sewer pipeline runs 6 to 9 feet underneath hilly terrain from the home's yard and through his neighbor's yard. The customer wanted a no-dig solution to preserve the yards.

**SOLUTION:** NuFlow successfully cleaned and lined this underground drain line without having to dig up any yard. After the blocked sanitary line was cleaned and reinstated, our pull-in-place liner was installed using existing access points. This structural liner forms a new, protective pipe that will prevent future failures.



### Christian Care Communities: Vertical Drain Stacks Rehabilitation

**LOCATION:** Louisville, Kentucky

**SITUATION:** Vertical drain stacks were clogged in the 10-story apartment building and leaking because of grease buildup. The system consists of 21 stacks with cast iron pipes 100 feet long and 3" in diameter.

**SOLUTION:** NuFlow was able to retrofit 10 floors at a time without having to relocate any residents or cause any destruction to the building. The drain stacks are now free of corrosion, buildup and pinhole leaks.

### Las Flores Tower Condominium: Drain and Potable Rehabilitation

**LOCATION:** Coronado Island, California

**SITUATION:** Part of the 10" cast iron drain line for Las Flores Tower was missing. A traditional, costly re-pipe would have caused destruction to the lobby, driveway, and street. The copper hot recirculation lines and vertical cast iron storm drains experienced corrosion and leaks.

**SOLUTION:** NuFlow cleaned and lined all 36-year-old pipe systems by accessing the existing connection points on the roof inside the parking garage. The drain line and storm drain lines were lined with our NuDrain pull-in-place structural lining and the potable system was lined with our blown-in epoxy coating.